



# While You Were Sleeping: The Loss of the Lewis Spacecraft

Leadership ViTS  
October 2007

Jim Lloyd  
Deputy Chief, Safety and Mission Assurance

**This and previous presentations are archived at:**

[http://pbma.nasa.gov/pbma\\_main\\_cid\\_584](http://pbma.nasa.gov/pbma_main_cid_584)



# The Failure

- The Lewis Spacecraft program was initiated in the early 1990's under NASA's **Faster, Better, Cheaper** (FBC) paradigm. As such, the contract (awarded to TRW) did not include government-specified technical requirements, performance or quality assurance standards.
- To save money TRW planned to employ only a single shift of flight controllers even for initial on-orbit checkout operations and used a heritage design attitude control system (ACS).

## Critical Event Timeline (EST)

### August 23

**2:51 a.m.** Launch from Vandenberg AFB to 300km parking orbit.

### August 25

**10:17 a.m.** Contact with the spacecraft is lost for three hours.

**1:17 p.m.\*\*** Contact reestablished; spacecraft 28° off the Sun; batteries at 43% depth of discharge (DOD). Spacecraft restored to Safe Mode, and observed as stable for four hours. Batteries fully charged.

**7:00 p.m.\*\*** Ground operations cease; staff begins nine hour rest period, electing not to request emergency backup ops team.

### August 26

**Early a.m.** Autonomous ACS attempts to maintain intermediate axis mode, result in excessive thruster firings and eventual ACS shut-down.

**4:02 a.m.** Edge-on spin discovered. Batteries at 72% DOD.

**6:17 a.m.** Flight Control attempts to arrest spacecraft rotation by firing ACS thrusters; contact never reestablished.

### September 28


**7:58 a.m.\*\*** Lewis re-enters earth's atmosphere and burns up.

\*\* estimated time




# Safe Mode

- During periods of inactivity Lewis used an ACS “Safe Mode” that orientated the solar panels towards the sun. As part of cost saving measures the “Safe Mode” was taken from a previous TOMS spacecraft that had a different mass distribution and solar panel arrangement.




Safe Mode



x-axis Spin

- During an attempt to stabilize Lewis the ACS inadvertently triggered a spin around the x-axis. The ACS system was controlled by a two axis gyro that provided no rate information about the x-axis.

- As mechanical energy dissipated Lewis underwent **Polhode** motion (by conservation of angular momentum). The spacecraft migrated from a spin about the x-axis to a spin about the z-axis with the edge of the solar panels facing the sun.
- Unable to maintain a charge on the batteries, the spacecraft shutdown and eventually burned up in the earth’s atmosphere.



Polhode



# Proximate Causes in Event Chain

---

- Inappropriate application and lack of peer review of attitude control system design.
- Inconsistent monitoring of spacecraft during crucial early operating phase.

## Causal Web – Underlying Issues

---

- Ineffective and inconsistent project leadership:
  - During a single 14 month period TRW saw four different Program managers and four General/Division managers.
- Incomplete and unsusained articulation and communication of **Faster, Better, Cheaper**:
  - By design, there were no government specified technical or quality assurance requirements. FBC relied on commercial best practices rather than traditional NASA management program control functions.
  - In the absence of higher level policy guidance NASA program executives struggled to define FBC in practical terms.
- Inadequate test and verification of heratige hardware/software:
  - The ACS verification process failed to address the improper application of software designed for a much different spacecraft.
  - FBC encouraged the use of heritage hardware and software, but verification procedures were slim and often only modeled a limited set of nominal scenarios.
- Insufficient budget to support robust ground operations:
  - Enormous cost containment pressures resulted in an understaffed ground support team that was off-duty during key early operational phases. An emergency backup team was not activated.
  - The decision to operate the early on-orbit mission with only a single shift ground control crew was not clearly communicated to senior TRW or NASA management.



# Lessons Learned for NASA

- Don't compromise safety and mission assurance reviews in the name of consolidation. There are simply no shortcuts in the fundamental life-cycle systems engineering disciplines.
- Ensure that schedule and budget goals are realistic and have sufficient margins to accommodate potential modifications or problems.
- Management sets the tone. Mission success cannot rely simply on process or textbook models. Consistent leadership is necessary for every project.
- Verify the correct implementation and use of heritage hardware and software.

